

TOP SECRET

12 JAN 1963

TOP SECRET 112109Z

(OUT 50447)

1963 JAN 11 21 28Z

HFS

CS

25X1

PRIORITY

REF: MISSION 9050 - M17

1. BINARY TIME MALFUNCTIONS OF FORWARD CAMERA WERE:

- A. LIGHT NO. 12 VERY DIM.
- B. LIGHT NO. 10 WAS WIRED INCORRECT AND SHOULD HAVE BEEN NO. 9.
- C. LIGHT NO. 9 SHOULD HAVE BEEN NO. 8.
- D. LIGHT NO. 8 SHOULD HAVE BEEN NO. 10.

2. BINARY INDEX LIGHTS AND CAMERA NUMBER ON AFT CAMERA FAILED AFTER PRE-FLIGHT. THIS GREATLY COMPLICATED BINARY READOUT.

3. NO OTHER LIGHT FAILURES OCCURRED.

TOP SECRET

CFN 0430 9050 M17 12 10 9 9 8 8 10 AFT

BT

125

NNNN

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1